

**The Glen of Pacific Grove Homeowners Association
24571 Silver Cloud Court Suite 101
Monterey, CA 93940
(831) 647-2442**

November 3, 2022

Dear Glen of Pacific Grove Owners and Residents:

We wanted to pass on an important reminder regarding the safety of your home. Dryer vents for clothing dryers can leave lint and other combustible materials in your dryer vent that extends to the roof. Per the community CC&Rs, this maintenance is the responsibility of the homeowner.

In addition to being a potential fire hazard, a clogged dryer vent can make it harder for your dryer to properly dry your clothing, resulting in longer cycles, wear on the appliance and higher energy costs.

We recommend having your dryer cleaned every year. Several board members and residents have had good luck with a local company who cleans dryer vents professionally. While you're under no obligation to use this company, it's here as a convenience to you.

You can read up on the hazards of untainted dryer vents here:

<https://www.consumerreports.org/clothes-dryer/how-to-prevent-dryer-fires-a6837216286/>

And here is who several of the community have used with good success:

<https://www.cypresssweeps.com>
831-642-0402

Thank you,

The Glen of Pacific Grove Board of Directors